

## Groundwater Section

SITE NAME: Norcon

REGULATED ✓

NONREGULATED

	<u>YES</u>	<u>NO</u>
RELEASE CONFIRMED:	<u>          </u>	<u>  ✓  </u>
CLEAN-UP INITIATED:	<u>          </u>	<u>          </u>
TANK(S) REMOVED:	<u>  ✓  </u>	<u>          </u>
RELEASE UNDER CONTROL:	<u>          </u>	<u>          </u>
CLEAN-UP COMPLETED:	<u>  ✓  </u>	<u>          </u>

TECHNICIAN:

DATE :

**COMMENTS :**

✓ USGS MAP  
✓ BASE MAP  
✓ ORIENTATION OF UST  
21' LENGTH OF UST  
8' DIAMETER OF UST  
8K VOLUME OF UST measured 6K  
gas MATERIAL STORED  
✓ SAMPLE LOCATIONS  
12' DEPTH OF SAMPLE  
floor SIDE OR FLOOR SAMPLE  
21-3' DEPTH OF TANK BURIAL  
auger HOW SAMPLE WAS COLLECTED  
ice SAMPLES PRESERVED AND TRANSPORTED  
✓ TOOLS DECONTAMINATED  
✓ TIME/DATE SAMPLE COLLECTED  
✓ TIME/DATE LAB RECEIVED  
5030 LAB RESULTS  
410 ✓ ANALYSIS METHOD  
✓ C.O.C.  
✓ REFERENCE TO SAMPLING POINT ON MAP  
3 CORRECT # OF SAMPLES  
Yes WITHIN 14 DAYS HOLDING TIME FOR SAMPLES  
Safeway TANK DESTINATION  
NA DISPOSITION OF SOIL  
12-7-93 REMOVAL DATE  
✓ COMPLETE GW/UST-2 FORM